

Tree code	Species		Location	Insp	Conditions	Recommendations	Priority
Sgl/250128 9	Malus sp.	Outside 37/39	Addison Way, Golders Green, London	SBR	Crown die back Fungal fruiting bodies - Ganoderma Trunk decay	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/250208 31	Malus sp.	Outside 141	Addison Way, Golders Green, London	SBR	Cracked & lifting bark	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/250300 55	Crataegus x prunifolia	Outside 50	Addison Way, Golders Green, London	SBR	Crown die back Cavity in crown Trunk cavity Trunk decay	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/250724 7	Prunus kanzan	Outside 13	Asmunds Hill, Golders Green, London	FGM	Trunk or branch cankers Fungal fruiting bodies - Ganoderma sp. @ base, multiple brackets Poor Foliage	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed RESI PD400 - Minimal sound wood detected	Cyclical
Sgl/251200 1	Prunus sargentii	Outside 64	Bancroft Avenue, East Finchley, London	FGM	Broken/lost leader Crown die back Trunk decay - Severe	Fell & Remove Prunus & Pollards Grind Oversize Hard Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/251220 6	Prunus sargentii	Outside 54	Bancroft Avenue, East Finchley, London	FGM	Basal cavity Basal Decay Crown decay Trunk decay	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface	Cyclical
Sgl/251452 14	Crataegus x prunifolia	Right Of 4	Beaufort Drive, East Finchley, London	KAT	Basal Decay Crown die back Fungal fruiting bodies Major deadwood Splits in major limb/trunk Trunk decay	Fell & Remove Grind Stump on Hard Surface Grind Oversize Hard Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/251832 9	Prunus sargentii	Outside 20	Bigwood Road, Golders Green, London	KAT	Dead	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/252372 18	Crataegus monogyna	Opposite 49	Brim Hill, East Finchley, London	FGM	Basal Decay Crown die back - Significant Fungal fruiting bodies	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/253076 68	Prunus kanzan	Outside 22	Brookland Rise, Golders Green, London	KAT	Basal Decay Crown die back Crown decay Cavity in crown Fungal fruiting bodies - ganoderma on the base sounds hollow all around	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/253080 16	Prunus kanzan	Between 35/37	Brookland Rise, Golders Green, London	SBR	Basal Decay Basal and trunk suckers Fungal fruiting bodies - Ganoderma	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical

Sgl/253112 76	Prunus kanzan	Side Of 2 Brookland	Brookland Rise, Golders Green, London	KAT	Basal Decay - hollow all around stem up to crown break and all scaffold branches also hollow Bark wound Crown decay Cavity in crown Cracked & lifting bark Fungal fruiting bodies - phellinus Trunk decay	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/259920 46	Prunus kanzan	Left Of Lp17	Brookland Rise, Golders Green, London	KAT	Basal Decay - Sounds very hollow all around buttress including Basal and trunk suckers Bark wound Fungal fruiting bodies - Ganoderma sp. in trunk cav. Raised roots/buttressing Trunk cavity Trunk decay	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Hard Surface	Cyclical
Sgl/259924 47	Prunus kanzan	Right Of Lp17	Brookland Rise, Golders Green, London	G&T	Dead	Fell & Remove Prunus & Pollards Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/253432 9	Acer ginnala	Outside 10	Brunner Close, Golders Green, London	KAT	Crown die back Cracked & lifting bark Splits in major limb/trunk	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/254216 5	Populus alba	Opposite lp1	Chandos Way, Golders Green, London	SBR	Crown die back	Fell & Remove Grind Stump on Soft Ground	Cyclical
Sgl/254322 35	Crataegus monogyna	Opposite 41-64	Chandos Way, Golders Green, London	FGM	Splits in major limb/trunk	Fell & Remove - Fell to ground level	Cyclical
Sgl/254512 4	Sorbus x thuringiaca Fastigiata	Outside 1	Church Mount, East Finchley, London	SBR	Crown die back Fungal fruiting bodies - Inonotus hispidus	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/254544 12	Prunus x hillieri Spire	Outside 19	Church Mount, East Finchley, London	G&T	Crown die back	Fell & Remove Prunus & Pollards Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/254600 26	Malus Tschonoskii	Right Of 28	Church Mount, East Finchley, London	FGM	Cracked & lifting bark Weak fork - Weak from previous tear and lost limb	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/255164 17	Prunus sp.	Opposite 58	Connaught Drive, Golders Green, London	SBR	Dead	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/255412 4	Prunus cerasifera Nigra	Outside 1	Cornwood Close, East Finchley, London	FGM	Fungal fruiting bodies - Ganoderma at base Suppressed	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface	Cyclical
Sgl/255504 2	Sorbus intermedia	Right Of lp1	Corringham Road, Golders Green, London	KAT	Basal cavity Basal Decay - sounds very hollow on road side Fungal fruiting bodies - ganoderma and ustulina inside cavity	Fell & Remove Grind Stump on Hard Surface Plant Tree in Soft Ground, Grass, Soil, Bed - sorbus	Cyclical

Sgl/255824 6	Crataegus laevigata Paul Scarlet	Opposite 2	Deansway, East Finchley, London	FGM	Basal cavity Basal Decay Crown die back Trunk cavity Trunk decay	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/256128 9	Crataegus crus gallii	Outside 37-42	Denison Close, East Finchley, London	SBR	Dead	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/256600 2	Prunus cerasifera Nigra	Outside 8	Dingwall Gardens, Golders Green, London	FGM	Crown decay Fungal fruiting bodies Leaning	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit - Amelanchier arborea	Cyclical
Sgl/256624 8	Prunus cerasifera Nigra	Outside 11	Dingwall Gardens, Golders Green, London	SBR	Basal cavity - Slight Fungal fruiting bodies - Ganoderma sp. @ 0.1m (multiple brackets)	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/256912 4	Crataegus laevigata Paul Scarlet	Right Of 11	Edmunds Walk, East Finchley, London	FGM	Basal Decay Crown die back Leaning	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/258344 12	Prunus sargentii	Side Of 46 Brim Hill	Gurney Drive, East Finchley, London	FGM	Basal Decay Bark wound Crown die back Crown decay	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/258372 19	Prunus avium	Outside 17	Gurney Drive, East Finchley, London	FGM	Basal cavity Basal Decay Fungal fruiting bodies - Laetiporus and Ganoderma sp. @ base/roots	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/258404 28	Prunus kanzan	Outside 29	Gurney Drive, East Finchley, London	SBR	Basal cavity Basal Decay - hollow stem from base to 1m Crossing branches Fungal fruiting bodies - Multiple Ganoderma sp. @ base	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/258408 29	Prunus sargentii	Outside 31	Gurney Drive, East Finchley, London	SBR	Basal cavity Basal Decay Crossing branches Fungal fruiting bodies - Ganoderma sp. @ base. Sounds hollow all around base	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/258448 40	Prunus kanzan	Outside 40	Gurney Drive, East Finchley, London	SBR	Basal Decay Fungal fruiting bodies - Multiple Ganoderma sp. @ base Sounds very hollow	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/258452 41	Sorbus aucuparia	Left Of 38	Gurney Drive, East Finchley, London	G&T	Dead	Fell & Remove Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/258464 44	Prunus kanzan	Outside 34a	Gurney Drive, East Finchley, London	SBR	Basal Decay Bacterial slime Fungal fruiting bodies - Ganoderma	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical

Sgl/258600 1	Prunus kanzan	Outside 2	Hampstead Gardens, Golders Green, Lond	FGM	Fungal fruiting bodies - Ganoderma sp. @ base in multiple areas Sound test indicates significant decay Planting - Resident Request Trunk decay	Extended Grind Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit - RR	Cyclical
Sgl/258624 7	Prunus kanzan	Outside 11	Hampstead Gardens, Golders Green, Lond	SBR	Crown die back Fungal fruiting bodies Poor Foliage Planting - Resident Request	Extended Grind Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit - RR	Cyclical
Sgl/258708 60	Betula papyrifera	Outside 47	Hampstead Way, Golders Green, London	KAT	Bacterial slime Dead Minor deadwood	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed - oak	Cyclical
Sgl/259028 46	Acer cappadocicum	Outside 28	Hampstead Way, Golders Green, London	KAT	Basal cavity Basal Decay Basal and trunk suckers Cavity in crown Fungal fruiting bodies - kreczmaria in cavity on road side fresh Minor deadwood Trunk defect	Extended Grind Fell & Remove Plant Tree in Soft Ground, Grass, Soil, Bed - Acer capp	Cyclical
Sgl/259216 5	Prunus sargentii	Outside 2	Harford Walk, East Finchley, London	SBR	Crown die back Dead	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Hard Surface	Cyclical
Sgl/259348 13	Prunus kanzan	Outside 18	Heathgate, Golders Green, London	FGM	Basal Decay - hollow butt Fungal fruiting bodies - Multiple Ganoderma sp. brackets @ base	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/259880 21	Prunus cerasifera Nigra	Outside 33	Hill Top, Golders Green, London	KAT	Basal Decay Bark wound Fungal fruiting bodies - ganoderma on road side	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/259884 22	Prunus cerasifera Nigra	Outside 35	Hill Top, Golders Green, London	KAT	Basal Decay Bark wound Crown die back Crown decay Fungal fruiting bodies - Ganoderma sp. @ base, phellinus	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/259968 31	Prunus cerasifera Nigra	Outside 76	Hill Top, Golders Green, London	SBR	Basal Decay Fungal fruiting bodies - Ganoderma sp. @ base Phellinus at pruning wound Large pruning wounds	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/259976 33	Alnus incana	Outside 72	Hill Top, Golders Green, London	SBR	Crown die back Cracked & lifting bark Fungal fruiting bodies - Ganoderma	Fell & Remove Grind Stump on Hard Surface Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical

Sgl/259988 36	Prunus avium	Opposite 19/21	Hill Top, Golders Green, London	SBR	Basal Decay Bacterial slime Crown decay Cavity in crown	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/260132 9	Prunus cerasifera Nigra	Outside 1	Hogarth Hill, Golders Green, London	FGM	Basal and trunk suckers Fungal fruiting bodies - Ganoderma lucidiun at base Planting - Resident Request	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/260340 11	Malus sp.	Outside 23	Holne Chase, East Finchley, London	SBR	Basal and trunk suckers Crown die back Fungal fruiting bodies - ganoderma - Sounds very hollow	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/260392 24	Malus sp.	Outside 49	Holne Chase, East Finchley, London	SBR	Codominant stems Fungal fruiting bodies - Multiple Ganoderma sounds mostly, hollow in some areas	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/260408 27	Malus sp.	Left Of 42	Holne Chase, East Finchley, London	FGM	Basal cavity Basal Decay Crown die back Fungal fruiting bodies - Ganoderma sp. multiple brackets f/w side at base	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/260432 33	Malus sp.	Outside 28	Holne Chase, East Finchley, London	FGM	Cavity in crown Fungal fruiting bodies - Polyporus squamosus in cavities Ganoderma at base	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/260464 41	Prunus cerasifera Nigra	Outside 8	Holne Chase, East Finchley, London	FGM	Bark wound Crown die back Fungal fruiting bodies - Phellinus in crown Ganoderma at base and stem	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/260784 21	Tilia sp.	Opposite 52	Hoop Lane, Golders Green, London	SBR	Basal and trunk suckers Cavity in crown Suppressed	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/260792 23	Platanus x hispanica	Opposite Crematori	Hoop Lane, Golders Green, London	SBR	Basal Decay Broken/lost leader Cracked & lifting bark Large pruning wounds Other - See memo - Defective trunk Trunk decay Unbalanced crown	Fell & Remove Grind Stump on Hard Surface	Cyclical
Sgl/261404 2	Alnus incana	Outside 1	Kingsley Close, East Finchley, London	FGM	Crown die back Direct Damage - To boundary wall Raised roots/buttreassing	Extended Grind Fell & Remove Plant Tree in Soft Ground, Grass, Soil, Bed - Prunus accolade	Cyclical
Sgl/261408 3	Prunus sargentii	Outside 3	Kingsley Close, East Finchley, London	FGM	Basal cavity Basal Decay - Severe when sound tested Fungal fruiting bodies - Multiple Ganoderma brackets around base	Extended Grind Fell & Remove Prunus & Pollards Plant Tree in Pre-Prepared Tree Pit - Prunus accolade	Cyclical

Sgl/261656 12	<i>Crataegus laevigata</i> Paul Scarlet	Outside 91	Kingsley Way South Section, Hampstead G	FGM	Basal Decay - Severe Crown die back Crown decay Cavity in crown	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/261692 21	<i>Sorbus x thuringiaca</i> Fastigiata	Outside 96	Kingsley Way South Section, Hampstead G	SBR	Bark wound Crown die back Major deadwood	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/261576 20	<i>Prunus avium</i>	Right Of 39	Kingsley Way, Hampstead Garden Suburb,	FGM	Basal Decay - Hollow all around Trunk or branch cankers Fungal fruiting bodies - ganoderma on the base	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/261764 33	<i>Prunus kanzan</i>	Between 60/62	Kingsley Way, Hampstead Garden Suburb,	G&T	Dead Fungal fruiting bodies Planting - Resident Request	Fell & Remove Plant Tree in Soft Ground, Grass, Soil, Bed - Prunus kanza, RR	Cyclical
Sgl/262096 25	<i>Tilia</i> sp.	Between 11/13	Linden Lea, East Finchley, London	FGM	Basal Decay Bark wound Fungal fruiting bodies - Ganoderma at base	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/262388 52	<i>Prunus sargentii</i>	Outside 37	Litchfield Way, Golders Green, London	FGM	Basal Decay - Hollow all around Fungal fruiting bodies - ganoderma Large pruning wounds	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/262400 55	<i>Prunus sargentii</i>	Outside 43	Litchfield Way, Golders Green, London	KAT	Basal cavity Basal Decay - Hollow all around stem and all buttress Crown decay Fungal fruiting bodies - Ganoderma sp. on stem roadside	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed - Prunus kanzan	Cyclical
Sgl/263648 13	<i>Prunus kanzan</i>	Outside 10	Meadway Close, Golders Green, London	FGM	None recorded..	Fell & Remove Prunus & Pollards Grind Oversize Hard Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/263188 22	<i>Robinia pseudoacacia</i>	Left Of 48	Meadway, Golders Green, London	FGM	Basal cavity Basal Decay Crown decay Cavity in crown Cracked & lifting bark Fungal fruiting bodies - decayed Laetiporus brackets on stem Large heavy branches Trunk decay Weak fork	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/263252 39	<i>Ailanthus altissima</i>	Side Of 17 Heathga	Meadway, Golders Green, London	FGM	Basal Decay - ResiPD tested. Minimal decay. Concern is now with root decay Crown die back - Significant. Likely linked eith basal decay and indicative of root decay Cracked & lifting bark	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical

Sgl/263900 12	Prunus cerasifera Nigra	Outside 12	Middleton Road, Golders Green, London	SBR	Basal cavity Basal Decay Crown die back Fungal fruiting bodies - Ganoderma	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit - Magnolia	Cyclical
Sgl/263912 1	Tilia sp.	Left Of Ip1	Middleton Road, Golders Green, London	KAT	Basal cavity Basal Decay - sounds hollow on 3/4 of trunk Fungal fruiting bodies - old kreczmaria fungus Leaning	Extended Grind Fell & Remove Prunus & Pollards Plant Tree in Soft Ground, Grass, Soil, Bed - ostria	Cyclical
Sgl/264756 15	Prunus sargentii	Outside 31	Norrice Lea, East Finchley, London	SBR	Basal cavity Basal Decay Fungal fruiting bodies - Ganoderma sp. on trunk	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Grind Stump on Soft Ground	Cyclical
Sgl/264816 30	Prunus sargentii	Outside 57	Norrice Lea, East Finchley, London	SBR	Basal and trunk suckers Cavity in crown Dead	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/264852 41	Crataegus laevigata Paul Scarlet	Outside 42	Norrice Lea, East Finchley, London	G&T	None recorded..	Fell & Remove Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/265240 36	Aesculus x carnea	Outside 82	Northway, Golders Green, London	SBR	Bacterial slime Crown die back Cracked & lifting bark Fungal fruiting bodies - Dryads saddle on large limb over road and Jelly ear on another large limb both about 5-6m. Large pruning wounds	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/265304 56	Sorbus x thuringiaca Fastigiata	Opposite 27	Northway, Golders Green, London	KAT	Bark wound Dead	Fell & Remove Grind Stump on Hard Surface Plant Tree in Hard Surface	Cyclical
Sgl/266296 67	Prunus padus	Outside 6	Ossulton Way, East Finchley, London	SBR	Crown die back	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/253832 6	Prunus kanzan	Right Of 1	South Square, Golders Green, London	FGM	Trunk cavity - Hollow stem Trunk defect Trunk decay Unbalanced crown	Extended Grind Fell & Remove Prunus & Pollards Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/266932 9	Prunus sargentii	Left Of 9-16 Bigwood	Southway, Hampstead Garden Suburb, Lor	FGM	None recorded..	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/266948 13	Prunus amanogawa	Outside 35	Southway, Hampstead Garden Suburb, Lor	FGM	Crown die back Fungal fruiting bodies - Ganoderma sp. @ base f/w side Trunk cavity Trunk decay	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/267012 30	Betula papyrifera	Between 68/70	Southway, Hampstead Garden Suburb, Lor	FGM	Crown die back - 80% dead	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical

Sgl/267500 1	Sorbus species	Opposite 4	St Edwards Close, Golders Green, London	FGM	Bark wound Crown decay - Significant amount of decay at crown break Leaning	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit - Prunus	Cyclical
Sgl/267624 7	Betula pendula	Outside 13	Sutcliffe Close, Golders Green, London	KAT	Crown die back Crown decay - Hollow in main union Cracked & lifting bark Trunk cavity Trunk defect Trunk decay - sounds hollow all the way around stem	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/112208 24	Ilex aquifolium	Outside 42	Temple Fortune Hill, Golders Green, London	FGM	None recorded..	Fell & Remove - Fell to ground level. No stump grinding needed	Cyclical
Sgl/268000 35	Prunus kanzan	Junction With Hoop	Temple Fortune Lane, Golders Green, London	SBR	Crown die back Fungal fruiting bodies - ganoderma	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface	Cyclical
Sgl/268060 7	Tilia sp.	Outside 94	Temple Fortune Lane, Golders Green, London	FGM	Basal Decay - major root decay Fungal fruiting bodies - Ustulina	Fell & Remove Grind Stump on Soft Ground	Cyclical
Sgl/268644 37	Aesculus hippocastanum	Right Of 30	The Bishops Avenue, East Finchley, London	FGM	Basal cavity Basal Decay Bacterial slime Bark wound Fungal fruiting bodies - ganoderma Trunk cavity Trunk decay	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/268688 47	Tilia sp.	Outside 1	The Bishops Avenue, East Finchley, London	GLE	Basal Decay - Significant hollowing Fungal fruiting bodies - Multiple Ganoderma sp. brackets at base	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/268736 60	Tilia sp.	Outside 27	The Bishops Avenue, East Finchley, London	FGM	Basal Decay Fungal fruiting bodies - Ganoderma at base Major deadwood	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/268764 67	Aesculus hippocastanum	Outside 37	The Bishops Avenue, East Finchley, London	FGM	Fungal fruiting bodies - Ganoderma @.5m Trunk decay - Some decay noted further to sound test	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/269100 31	Betula pendula	Opposite 16	Thornton Way, Golders Green, London	FGM	Bacterial slime Crown die back Trunk defect	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/269348 3	Crataegus laevigata Paul Scarlet	Between 32/34	Vivian Way, East Finchley, London	FGM	Crown die back Leaning	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/269384 12	Crataegus laevigata Paul Scarlet	Outside 8	Vivian Way, East Finchley, London	FGM	Basal cavity Basal Decay Trunk cavity Trunk decay	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical

Sgl/269932 19	Malus sp.	Outside 52	Wildwood Road, Golders Green, London	FGM	Crown die back Fungal fruiting bodies Trunk decay	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit - Malus rudolph	Cyclical
Sgl/270008 38	Prunus cerasifera Nigra	Opposite Ip18	Wildwood Road, Golders Green, London	SBR	Crown die back Fungal fruiting bodies - Phelinus - Trunk sounds hollow	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface	Cyclical
Sgl/270128 8	Prunus kanzan	Between 170/172	Willifield Way, Golders Green, London	FGM	Basal Decay Cracked & lifting bark Fungal fruiting bodies - Ganoderma sp. @ base Raised roots/buttrressing Trunk decay - Significant when sound tested	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Grind Oversize Hard Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/270132 9	Malus sp.	Outside 166	Willifield Way, Golders Green, London	FGM	Basal Decay Cavity in crown Fungal fruiting bodies - Ganoderma at base	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/270196 20	Malus sp.	Outside 86	Willifield Way, Golders Green, London	FGM	Basal cavity Trunk cavity Trunk decay	Fell & Remove Grind Stump on Hard Surface Grind Oversize Hard Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/270272 41	Prunus cerasifera Nigra	Outside 20/22	Willifield Way, Golders Green, London	FGM	Crown die back Trunk cavity Trunk decay Weak fork	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/270276 42	Prunus cerasifera Nigra	Right Of 20	Willifield Way, Golders Green, London	FGM	Fungal fruiting bodies - Ganoderma at base Leaning	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/270324 54	Crataegus laevigata Paul Scarlet	Outside 15	Willifield Way, Golders Green, London	SBR	Basal cavity Basal Decay Cavity in crown Trunk decay - Sounds like Extensive decay.	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/270328 55	Crataegus laevigata Paul Scarlet	Outside 19	Willifield Way, Golders Green, London	SBR	Basal cavity Basal Decay Cavity in crown	Fell & Remove Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical
Sgl/270420 76	Malus Rudolph	Opposite 106	Willifield Way, Golders Green, London	SBR	Crown die back Fungal fruiting bodies	Fell & Remove Grind Stump on Hard Surface Plant Tree in Hard Surface	Cyclical
Sgl/270432 80	Malus sp.	Outside 111	Willifield Way, Golders Green, London	SBR	Crown decay Cavity in crown Trunk cavity Trunk decay	Fell & Remove Grind Stump on Hard Surface Plant Tree in Hard Surface	Cyclical
Sgl/270460 87	Prunus cerasifera Nigra	Outside 147	Willifield Way, Golders Green, London	FGM	Crown decay Fungal fruiting bodies - Phellinus sp. Multiple brackets in crown	Fell & Remove Prunus & Pollards Grind Stump on Hard Surface Plant Tree in Pre-Prepared Tree Pit	Cyclical

Sgl/270600 1	Prunus kanzan	Left Of 96	Winnington Road, East Finchley, London	FGM	Basal Decay - Significant further to sound test Fungal fruiting bodies - Ganoderma at base Trunk decay	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/270756 40	Nothofagus antarctica	Outside 32	Winnington Road, East Finchley, London	SBR	Dead	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/270820 56	Betula pendula	Outside 6	Winnington Road, East Finchley, London	SBR	Dead	Fell & Remove Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical
Sgl/271024 109	Prunus kanzan	Outside 85	Winnington Road, East Finchley, London	FGM	Fungal fruiting bodies - Ganoderma at base Significant decay noted from sound test	Fell & Remove Prunus & Pollards Grind Stump on Soft Ground Plant Tree in Soft Ground, Grass, Soil, Bed	Cyclical